




Xerox® Versant® 80 180 2100 3100 Heat Belt Position Sensor Assembly 130K79730 130K79731 130K79732



sales@xentair.com

Price: £368.00

Location:

Stock: 0

If you are getting error codes 099-338 099-339 or 099-340 belt walk errors.

For Use In Xerox® Versant® 80 180 2100 3100

Part Numbers 130K79730 130K79731 130K79732

Contents 1 x heat belt position sensor assembly per carton.

Xentair International Ltd - www.xentair.com - sales@xentair.com - +44 (0) 1256 886 420